

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2019

Submitted Date:

03/25/2019

Document Number:

696100629

FIELD INSPECTION FORM

Loc ID 302891 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285253	WELL	PR	02/12/2010	OW	123-29983	LUCCI B 1-25	SI

General Comment:

This is a WELL & BATTERY Inspection.
Well is SI.
Centralized Battery serves 4 Location IDs (302891, 310121, 327189, 327190).
Follow-up to FIR #691200557 dated 10/03/2018.
1 of 1 Corrective Actions has been addressed.
North & South produced water vaults. Capacity is NOT legible.
Post legible capacity labels on produced water vaults. Produced H2O vaults capacity labels NOW Legible. See photos #5-6.
South & middle crude oil tanks. Contents & Capacity labeling is faded. NOT legible.
Post legible contents & capacity labels on crude oil tanks. Crude oil tanks Contents / Capacity labels NOW Legible. See photos #3-4.

Weather: Clear, w/ muddy areas.
No Corrective Actions observed on this FIR.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	<p>From prior FIR: North & South produced water vaults. Capacity is NOT legible. Post legible capacity labels on produced water vaults. South & middle crude oil tanks. Contents & Capacity labeling is faded. NOT legible. Post legible contents & capacity labels on crude oil tanks.</p> <p>This FIR: Produced H2O vaults capacity labels NOW Legible. See photos #5-6. Crude oil tanks Contents / Capacity labels NOW Legible. See photos #3-4.</p>		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:			Date:

Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	ECD scrubbers		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	ECD #1: Controls crude oil tanks VOCs. ECD #2: Controls separator VOCs. Pilots: ON		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 4 Location IDs (302891, 310121, 327189, 327190).				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	CONCRETE SUMP/VAULT			
Comment:						
Corrective Action:				Date:		

Paint						
Condition						
Other (Content)						
Other (Capacity)	48 Bbls.					
Other (Type)						

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:				Shares berms w/ crude oil tanks.		
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		40.423118,-104.501079	
Comment:				Equalizer line connects North & Middle crude oil tanks.		
Corrective Action:				Date:		

Paint						
Condition						
Adequate						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:				Shares berms w/ produced H2O vaults.		
Corrective Action:				Date:		

Venting:						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		

Flaring:						
Type						
Comment:						

Corrective Action:

Date:

Inspected Facilities

Facility ID: 285253 Type: WELL API Number: 123-29983 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Observed production valves shut.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100631	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4773506