

**Inspection Photos**  
**Location Name: MV SMITH 31**  
**Location ID: 05-103-05344**  
**Inspection: 679703476**



**Photo 1. Location looking northeast.**



**Photo 2. Tank battery.**

Inspection Photos  
Location Name: MV SMITH 31  
Location ID: 05-103-05344  
Inspection: 679703476



Photo 3. Unmarked deadman



Photo 4. Tank sign missing capacity of 300 bbl.

## Inspection Photos

Location Name: MV SMITH 31

Location ID: 05-103-05344

Inspection: 679703476



Photo 5. Casing valve leaking gas.



Inspection Photos  
Location Name: MV SMITH 31  
Location ID: 05-103-05344  
Inspection: 679703476







Photo 4. Casing valve in infrared with a FLIR GF320 camera.

Photo 5. Casing valve in infrared HSM with a FLIR GF320 camera. (Wind blowing left to right)

**Inspection Photos**  
**Location Name: MV SMITH 31**  
**Location ID: 05-103-05344**  
**Inspection: 679703476**



**Photo 6. Well head in infrared with a FLIR GF320 camera.**

**Photo 7. Well head in infrared HSM with a FLIR GF320 camera. (Wind blowing left to right)**