

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2019

Submitted Date:

03/20/2019

Document Number:

687904139**FIELD INSPECTION FORM**Loc ID 306788 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264755	WELL	PR	04/01/2018	GW	067-08760	ZELLITTI 34-9 34-2	PR
417836	WELL	PR	11/21/2010	GW	067-09819	ZELLITTI 34-9 34-4	PR

General Comment:[Downloadable photos at the end of this inspection report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road through gates.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Missing tank labels on 30 BBL produced water tank that is full but says not in use.			
Corrective Action:	Comply with Rule 210.d.			Date: 04/20/2019
Type	WELLHEAD			
Comment:	Framed metal sign at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information current. (505) 324-5170			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Belt gaurd taken off running pump jack and not re-installed.			
Corrective Action:				Date:
Type	UNUSED EQUIPMENT			
Comment:	unused control valve sitting against separator.			
Corrective Action:	Comply with 603.f.			Date: 04/20/2019
Type	OTHER			
Comment:	Vacuum breaker on separator is leaking fluid.			
Corrective Action:	Comply with Rule 605.d.			Date: 03/22/2019
Type	UNUSED EQUIPMENT			
Comment:	30 BBL tank sitting on location not connected or being used. Tank is full with no secondary containment, spill prevention or wildlife protection.			
Corrective Action:	Comply with 603.f. or 605.a.(4)			Date: 04/20/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pump jack.			
Corrective Action:				Date:

Equipment:			corrective date
Type: Other	# 1		
Comment:	Sound walls.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Zellitti #34-4 Pump jack head has been removed and now has a plunger lift. Pump jack is unused equipment.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/20/2019
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	264755	Type:	WELL	API Number:	067-08760	Status:	PR	Insp. Status:	PR
Facility ID:	417836	Type:	WELL	API Number:	067-09819	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass	Gravel	Pass			
Waddles	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401979940	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769102
687904140	Vacuum breaker leaking	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769096
687904141	Unused tank that is full	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769097
687904142	Unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769098
687904143	Unused pump jack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769099