

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2019

Submitted Date:

03/20/2019

Document Number:

695100369

**FIELD INSPECTION FORM**

Loc ID 309402 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	<a href="#">All Inspections</a>
Mack, Ronald		ronaldmack@tcenergy.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
164	WELL	PR	01/21/2009	GW	071-09485	GOLDEN EAGLE 28-01	PR
300259	PIT	AC	12/16/2008		-	GOLDEN EAGLE 28-01	AC

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Well sign on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Ancillary equipment	# 1			
Comment:	Telemetry equipment			
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:	3 marked 1 marker down on the ground next to the northeast anchor.			
Corrective Action:	comply with rule 902.b.	Date:	04/20/2019	
Type: Prime Mover	# 1			
Comment:				
Corrective Action:		Date:		
Type: Progressive Cavity	# 1			
Comment:				
Corrective Action:		Date:		
Type: Gas Meter Run	# 1			
Comment:	LAST CAL. 12/7/18			
Corrective Action:		Date:		
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	breadenhead is not plumbed to surface			
Corrective Action:		Date:		
Type: Compressor	# 1			
Comment:	WELL APPEARS TO BE PRODUCING ON A VACUUM. THERE IS NO FORM 4 SUNDRY NOTICE ON RECORD.			

Corrective Action: <b>COMPLY WITH RULE 331</b>	Date: <b>04/20/2019</b>
--	-------------------------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	STEEL AST		37.149090,-104.886180

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	30 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	<50 BBLs	STEEL AST		

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	15 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	NFPA sticker is not legable.
Corrective Action:	replace sign to comply with Rule 210.d.
	Date: <b>04/20/2019</b>

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 164 Type: WELL API Number: 071-09485 Status: PR Insp. Status: PR

Facility ID: 300259 Type: PIT API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: YES      Pit ID: 300259      Lat: 37.148836      Long: -104.886740

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: Adequate

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Other      Fencing Condition: Adequate

Comment: electric fence

Corrective Action

Date:

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment: none

Corrective Action

Date:

Anchor Trench Present: YES      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: no freeboard marker

Corrective Action

comply with rule 902.b.

Date: 04/20/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401979790	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769031">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769031</a>
695100371	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769021">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769021</a>