

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2019

Submitted Date:

03/27/2019

Document Number:

685100721**FIELD INSPECTION FORM**

Loc ID 441811	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 8 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10459</u> Name of Operator: <u>EXTRACTION OIL & GAS INC</u> Address: <u>370 17TH STREET SUITE 5300</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				
Contact Information:				

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441807	WELL	PR	07/01/2016	LO	123-41517	Fairview 10	PR
441808	WELL	PR	07/01/2016	LO	123-41518	Fairview 7	PR
441809	WELL	PR	07/01/2016	LO	123-41519	Fairview 6	PR
441810	WELL	PR	07/01/2016	LO	123-41520	Fairview 9	PR
441812	WELL	PR	07/01/2016	LO	123-41521	Fairview 5	PR
441813	WELL	PR	07/01/2016	LO	123-41522	Fairview 3	PR
441814	WELL	PR	07/01/2016	LO	123-41523	Fairview 4	PR
441821	WELL	PR	07/01/2016	LO	123-41524	Fairview 11	PR
441822	WELL	PR	07/01/2016	LO	123-41525	Fairview 8	PR
442099	WELL	PR	06/01/2016	LO	123-41666	Fairview 2	PR
442100	WELL	DA	02/07/2018	LO	123-41667	Fairview 1	DA
455337	SPILL OR RELEASE	CL	06/07/2018		-	Fairview 5-I	CL

General Comment: <div style="height: 40px;"></div>
--

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fence around wellheads on location.

Corrective Action:

Date:

Type

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: VRU

1

Comment:

Corrective Action:

Date:

Type: Gathering Line

1

Comment:

Corrective Action:

Date:

Type: Other

10

Comment: Wells appear to have bradenhead plumbed to surface.

Corrective Action:

Date:

Type: Other

#

Comment: 4 wells appear to have gas lift on them.

Corrective Action:

Date:

Type: Emission Control Device

5

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

10

Comment:

Corrective Action:		Date:	
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Gas lift compressor on location.		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		40.166090,-105.035070
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	<100 BBLs	PBV CONCRETE		40.166090,-105.035070
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	1 Shares containment with oil AST tanks.			
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	400 BBLs	STEEL AST		40.166090,-105.035070
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>441807</u>	Type: <u>WELL</u>	API Number: <u>123-41517</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441808</u>	Type: <u>WELL</u>	API Number: <u>123-41518</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441809</u>	Type: <u>WELL</u>	API Number: <u>123-41519</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441810</u>	Type: <u>WELL</u>	API Number: <u>123-41520</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441812</u>	Type: <u>WELL</u>	API Number: <u>123-41521</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441813</u>	Type: <u>WELL</u>	API Number: <u>123-41522</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441814</u>	Type: <u>WELL</u>	API Number: <u>123-41523</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441821</u>	Type: <u>WELL</u>	API Number: <u>123-41524</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>441822</u>	Type: <u>WELL</u>	API Number: <u>123-41525</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>442099</u>	Type: <u>WELL</u>	API Number: <u>123-41666</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>442100</u>	Type: <u>WELL</u>	API Number: <u>123-41667</u>	Status: <u>DA</u>	Insp. Status: <u>DA</u>
Facility ID: <u>455337</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>CL</u>

Producing Well

Comment:		
Corrective Action:		Date: <input type="text"/>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Issues with erosion from document # 682402400 appear to be addressed.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	03/27/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100722	Loc Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4774814