

Inspection Photos
Location Name: Oxbow 0880 S29
API: 05-057-06618



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Oxbow 0880 S29
API: 05-057-06618



Photo 2. Additive spilled in foreground, improper storage (uncovered) in background.



Photo 3. Improper (uncovered) additive storage and spill.

Inspection Photos
Location Name: Oxbow 0880 S29
API: 05-057-06618



Photo 4. Spilled additive pushed against and into location perimeter berm.



Photo 5. Additives without secondary containment.

Inspection Photos
Location Name: Oxbow 0880 S29
API: 05-057-06618



Photo 6. Hoses stored without secondary containment.



Photo 7. Non-reportable spill.