

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2019

Submitted Date:

03/27/2019

Document Number:

689802428

FIELD INSPECTION FORM

Loc ID 458790 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
462055	WELL	DG	03/09/2019		057-06618	Patriot 0880 13-32H5	DG

General Comment:

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Mud and cuttings additives not properly stored. No containment and material spilled. Hoses stored without containment. Drips (spills). Inspector informed company man of issues observed during inspection.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/27/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 462055 Type: WELL API Number: 057-06618 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Cyclone 33 Pusher/Rig Manager: Frank
Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: Twin Enviro

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
				Covering Materials	Fail	Additives not covered.
		Gravel				
				Vehicle Tracking	Fail	Tracking onto hwy 14.
				Material Handling And Spill Prevention	Fail	

Comment: Mud and cuttings additives not properly stored. No containment and material spilled. Tracking of sediment off location, through Grizzly location and onto CO State Highway 14.

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority. Install or repair required BMPs per Rule 1002.f.

Date: 03/27/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802429	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775199