

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Reclaimed area on hillside near point source of Spill/Release Point ID #458834.



Reclaimed area along flow path of Spill/Release Point ID #458834.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



High Flume siphon inlet with residual E and P waste.



Oil stained concrete at High Flume siphon inlet.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Stained concrete adjacent to High Flume siphon bypass.



Residual impacts along High Flume siphon bypass.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Impacted soil and vegetation along High Flume siphon bypass.



Impacted soil and vegetation remain along High Flume siphon bypass.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Reclaimed area near point source of release.



Reclaimed area along flow path of release.