

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2019

Submitted Date:

03/27/2019

Document Number:

685100731**FIELD INSPECTION FORM**

Loc ID 311412 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251766	WELL	PR	07/27/1998	GW	123-19570	MCCOY 13-5	PR
418020	WELL	AL	06/26/2013	LO	123-31812	MCCOY 0-6-5	AL
418042	WELL	AL	02/24/2016	LO	123-31824	MCCOY 2-8-5	AL
452240	TANK BATTERY	AC	09/20/2017		-	McCoy 13-5 battery	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type TANK BATTERY

Comment: 6' chain link fence with barb wire.
Unused unmarked riser between oil tanks. See pic 6

Corrective Action: Comply with Rule 603.f .

Date: 04/27/2019

Type WELLHEAD

Comment: Red AG fence around wellhead. Weeds bunched up around fencing. See pic 2

Corrective Action: Comply with Rule 603.f .

Date: 04/06/2019

Type SEPARATOR

Comment: 6' Chain link fence with barb wire around separator, gas meter run, and ECD.
Unused unmarked riser south of ECD in fencing.. See pic 8

Corrective Action: Comply with Rule 603.f .

Date: 04/27/2019

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: VRU

1

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

2

Comment:

Corrective Action:

Date:

Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Bradenhead on wellheads appear to be plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		40.167340,-104.921390
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with oil tanks.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	200 BBLs	STEEL AST		40.167340,-104.921390
Comment:	What appears to be leaking hammer union, and bull plug in containment of oil tanks. See pic 5&7				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 04/27/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 251766 Type: WELL API Number: 123-19570 Status: PR Insp. Status: PRFacility ID: 418020 Type: WELL API Number: 123-31812 Status: AL Insp. Status: ALFacility ID: 418042 Type: WELL API Number: 123-31824 Status: AL Insp. Status: ALFacility ID: 452240 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday March 27 2019 at approximately 1100 I, Inspector Justin Medina, conducted an on-site inspection at McCoy 13-5 at 123-19570 in Weld County Colorado. While there, I observed Producing wells.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused unmarked riser between oil tanks. See pic 6</p> <p>Comply with Rule 603.f . 4-27-19</p> <p>Red AG fence around wellhead. Weeds bunched up around fencing. See pic 2</p> <p>Comply with Rule 603.f . 4-6-19</p> <p>Unused unmarked riser between oil tanks. See pic 6</p> <p>Comply with Rule 603.f .4-27-19</p> <p>What appears to be leaking hammer union, and bull plug in containment of oil tanks. See pic 5&7</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 4-27-19</p> <p>I spoke with Company representative:</p> <p>Asked company representative to unlock fencing around separator, and was denied access. Representative stated that their policy is if you do not have a key you cannot have access to equipment. Asked company representative for business card and stated he did not have one and drove away. Found unlocked gate for access, and unlocked one padlock with keys.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>Inspection document # 678301112 CA appear to have been addressed, see pic 9</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	medinaj	03/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100732	Loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775340