

Construction and Storm Water Inspection

March 22, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 455317

Inspection Document #: 674902694

Weld County, CO

NWSE Section 7 T1S R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 1. Photo taken from the southern perimeter of the location, facing West. Photo illustrates a ditch and berm BMP that is being installed around the perimeter of the location.



Photo 2. Photo taken from the southern perimeter of the location, facing West. See comments from Photo 1. An additional silt fence BMP is installed on the southern edge of the location.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 3. Photo taken from the southern perimeter of the location, facing West. Appears the operator is installing a culvert through the USFWS National Wetlands Inventory mapped Riverine System (R4SBC).



Photo 4. Photo taken from the southern perimeter of the location, facing Southeast. Appears the operator is installing a culvert through the USFWS National Wetlands Inventory mapped Riverine System (R4SBC).

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 5. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 4.



Photo 6. Photo taken from the western perimeter of the location, facing South. Appears the Operator has installed a sediment trap with a temporary stabilized outlet.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 7. Photo taken from the western perimeter of the location, facing North. See erosion comments from Photo 9.



Photo 8. Photo taken from the western perimeter of the location, facing South. See comments from Photos 1 and 6.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 9. Photo taken from the western perimeter of the location, facing North. The middle ground of the Photo depicts erosion observed on location with apparent sediment accumulation within the sediment trap. The background of the Photo illustrates the topsoil stockpile has not been temporarily stabilized.



Photo 10. Photo taken from the western perimeter of the location, facing South. See erosion comments from Photo 9.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 11. Photo taken from the western perimeter of the location, facing North. See topsoil comments from Photo 9.



Photo 12. Photo taken from the northwestern perimeter of the location, facing East. See topsoil comments from Photo 9.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/1S68W7

Location ID: 455317



Photo 13. Photo taken looking at the access road on the east end of the location off Lowell Boulevard, facing East. Photo depicts a culvert being installed.



Photo 14. Photo taken from the access road, facing North. See comments from Photos 13.