

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 1 location picture



Photo 2 Truck transfer area

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 3 Unused equipment : Recycling battery



Photo 4 Unused equipment : Recycling battery inspection plates have been removed

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 5 Unused equipment : Recycling battery. Tank sign and NFPA placard unreadable or missing



Photo 6 Unused equipment Acid tank, NFPA placards unreadable and faded, no volume sign ,no bull plug on load line, storm water issue with no secondary containment

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 7 Unused equipment Acid tank, NFPA placards unreadable and faded, no volume sign ,no bull plug on load line, storm water issue with no secondary containment



Photo 8 Mechanical issue: Valve appears to be leaking on acid tanks . Storm water issues due to no secondary containment

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 9 Unused equipment Acid tank, no bull plug on load line, storm water issue with no secondary containment



Photo 10 Unused equipment : Recycling battery. Tank sign and NFPA placard unreadable or missing

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 11 Active injection facility




Photo 12 Active Injection facility Tank sign and NFPA placard unreadable or missing

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 13 Stained soil around active injection battery



Photo 14 Stained soil outside door of active injection pump building

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 15 Stained soil outside opposite side of active injection pump building



Photo 16 Unused unmarked riser

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 17 Active Injection facility Tank sign and NFPA placard unreadable or missing



Photo 18 Active Injection facility Tank sign and NFPA placard unreadable or missing

Inspection Photos
Location Name: LSWD #1
Facility ID: 159372



Photo 19 Inadequate tracking pad BMP



Photo 20 Sediment being carried onto county road 34 from trucks exiting facility