

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2019

Submitted Date:

03/21/2019

Document Number:

682600649

FIELD INSPECTION FORM

Loc ID 322215 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 44390
Name of Operator: JAVERNICK OIL
Address: 3040 E MAIN
City: CANON CITY State: CO Zip: 81212

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mehennett, Tom	(719) 275-3040/ (505) 330-1328	tbm3040@gmail.com	All Inspections
Costa, Ryan		ryan.costa@state.co.us	
Axelson, John		john.axelson@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Javernick, James	719-275- 3040/719-671- 3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209871	WELL	PR	11/20/1996	OW	043-05088	TEMPLETON 1	EI

General Comment:

This is an environmental follow up inspection to COGCC inspection 693900047. Any corrective actions from previous inspections that have not been performed are still required.

COGCC inspection 693900047 identified an environmental corrective action to stop leak at wellhead and a possible historic spill in cut bank next to wellhead. This follow up inspection found the free fluid from leaking wellhead to be removed but a new stuffing leak has developed. Operator shut in well upon arrival to begin repairs and fix leak.

Investigation into soils in cut bank did not find stained soil or a hydrocarbon odor in the soil in excavations 12 inches deep. Previous observations of possible hydrocarbon stained soil likely due to wet carbonaceous soils at the time of previous inspection.

Follow up inspection to document compliance with other corrective actions from inspection 693900047 still required.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment: Small leak from wellhead observed upon arrival. Operator shut in well to address leak.				
Corrective Action: 30 days to remove stained soil around wellhead.			Date:	<u>04/23/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 209871 Type: WELL API Number: 043-05088 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401980636	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769796
682600653	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4769792