

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2019

Submitted Date:

03/20/2019

Document Number:

685100675

FIELD INSPECTION FORMLoc ID 335860 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		Cogcc.inspections@crestone pr.com	
,		dnr_cogccengineering@state. co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293762	WELL	SI	12/01/2018	OW	014-20647	BICKLER 24-34	SI
293770	WELL	SI	12/01/2018	GW	014-20645	BICKLER 4-6-34	SI
293771	WELL	SI	12/01/2018	GW	014-20646	BICKLER 23-34	SI
293772	WELL	SI	12/01/2018	GW	014-20648	BICKLER 4-4-34	SI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds around fenced location appear to be taking over natural vegetation. Refer to document 682400214 previous inspection with same corrective action from 1/29/2016		
Corrective Action:	Comply with rule 603.f	Date:	01/29/2016

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

				corrective date
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: VRU	# 1			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 4			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	PBV FIBERGLASS		40.007010,-104.990120	
Comment:						
Corrective Action:					Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares containment with oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.007010,-104.990120
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: <u>293762</u>	Type: <u>WELL</u>	API Number: <u>014-20647</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>293770</u>	Type: <u>WELL</u>	API Number: <u>014-20645</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>293771</u>	Type: <u>WELL</u>	API Number: <u>014-20646</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>293772</u>	Type: <u>WELL</u>	API Number: <u>014-20648</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: All wells on location appear to be shut in.
Wells appear to be shut in. No MIT on record.
No current MIT on record or delinquent as required by Rule 326

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 04/01/2019

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On March 19, 2019 at approximately 1400 I, Inspector Justin Medina, conducted an on-site inspection at Crestone Peak 014-20648 in Broomfield County Colorado. While there, I observed shut in wells. The following possible compliance issues were observed.</p> <p>Weeds around fenced location appear to be taking over natural vegetation. Refer to document 682400214 previous inspection with same corrective action from 1/29/2016</p> <p>Wells appear to be shut in. No MIT on record. No current MIT on record or delinquent as required by Rule 326</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	03/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401981121	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4770303
685100678	location pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4770293