

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2019

Submitted Date:

03/11/2019

Document Number:

688401431**FIELD INSPECTION FORM**
 Loc ID 437854 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email             | Comment                            |
|--------------|-------|-------------------|------------------------------------|
| Watt, Dustin |       | dwatt@hpres.com   | <a href="#">Sr. EHS Specialist</a> |
| Barber, Matt |       | mbarber@hpres.com | <a href="#">All Inspections</a>    |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------------|-------------|
| 437850      | WELL | PR     | 03/01/2018  | OW         | 123-39734 | Anschutz Equus Farms 4-62-33-0108CH2 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Location sign        |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT  |       |            |
| Comment:           | Unused equipmt: HYD pumping unit, parts and polish rod next to PU unit. Load line hoses in and around TNK BTRY. Oil tank and separator on edge of location.                 |       |            |
| Corrective Action: | Comply with rule 603 f  | Date: | 04/11/2019 |
| Type               | OTHER   |       |            |
| Comment:           | Materials handling and spill prevention procedures and practices.   |       |            |
| Corrective Action: | Comply with COGCC rule 1002 F (2) B   | Date: | 04/11/2019 |
| Type               | OTHER   |       |            |
| Comment:           | Mechanical: crude oil lines inside containment (pic 22) appear to be leaking  |       |            |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 04/11/2019 |
| Type               | STORAGE OF SUPL   |       |            |
| Comment:           | improper storage of loadline hoses  |       |            |
| Corrective Action: | Comply with rule 603 f  | Date: | 04/11/2019 |
| Type               | TRASH   |       |            |
| Comment:           | Unused 5 gal buckets, pellets, snow fence, T post in and around TNK BTRY. 5 Gal buckets inside separator house. diapers on VRU skids.                                       |       |            |
| Corrective Action: | Comply with rule 603 f  | Date: | 03/25/2019 |
| Type               | OTHER   |       |            |
| Comment:           | stained soil : in and around multiple areas of TNK BTRY, transfer pump outside of compressor for oil  |       |            |
| Corrective Action: | Properly treat or dispose of oily waste in accordance with 907.e  | Date: | 04/11/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                                   |  |       |                 |
|-----------------------------------|--|-------|-----------------|
| <b>Equipment:</b>                 |  |       | corrective date |
| Type: Flare                       | # 2  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Bird Protectors             | # 6  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Horizontal Separator        | # 2  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Ancillary equipment         | # 4  |       |                 |
| Comment:                          | Electric pannels                             |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Other                       | #  |       |                 |
| Comment:                          | Braden head appears to be plumbed to surface |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Gas Meter Run               | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: VRT                         | # 3  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Emission Control Device     | # 3  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Horizontal Heated Separator | # 4  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: LACT                        | # 3  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Compressor                  | # 1  |       |                 |
| Comment:                          |  |       |                 |

|                          |     |       |  |
|--------------------------|-----|-------|--|
| Corrective Action:       |     | Date: |  |
| Type: Plunger Lift       | # 1 |       |  |
| Comment:                 |     |       |  |
| Corrective Action:       |     | Date: |  |
| Type: VRU                | # 5 |       |  |
| Comment:                 |     |       |  |
| Corrective Action:       |     | Date: |  |
| Type: Vertical Separator | # 5 |       |  |
| Comment:                 |     |       |  |
| Corrective Action:       |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 3 | 400 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                                | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
|                    |   |                     |                     |             |
| Comment:           | shares containment with crude oil tanks |                     |                     |             |
| Corrective Action: |   |                     |                     | Date:       |

| Contents           | #  | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|----|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 15 | 400 BBLs | STEEL AST |         | 40.274342,-104.336968 |
| Comment:           |    |          |           |         |                       |
| Corrective Action: |    |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |
|--|
|  |
|--|

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 437850 | Type: | WELL | API Number: | 123-39734 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             | PR     |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Mulching         | Pass            |                         |                       |               |                          |         |
| Sediment Traps   | Pass            |                         |                       |               |                          |         |
| Waddles          | Pass            |                         |                       |               |                          |         |
| Drains           | Pass            |                         |                       |               |                          |         |
| Rip Rap          | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| <p><b>COGCC Inspection Report Summary</b></p> <p>On Monday March 11 at approximately 1200hrs, I, Randy Silver, conducted an on-site inspection at Anschutz Equus Farms #4-62-33-108CH2, A Highpoint Operating corporation, at API# 123-39734 in Weld county Colorado. While there, I observed a production location. I was performing a follow up inspection to an accident document filed with the COGCC Doc# 401961128. I did not see any evidence of fire in or around gas compressor. See Photo's 5,6,7.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment: HYD PU, parts and polish rod, load line hoses, storage oil tank, separator and unknown create. Rule 603f CAD of 4-11-19. See attached photo's 2,3,4,15,24,31,33,37,38 and 39.-</p> <p>Trash: 5gal buckets and pellets inside TNK BTRY containment. 5gal buckets inside separator house.Snow fence and T posts outside TNK BTRY containment. Rule 603 f CAD of 3-25-19. See attached photo's 14,18,25,34,35.</p> <p>Mechanical issue: oil line inside TNK BTRY. Rule 605 d CAD of 4-11-19. See attached photo 22.</p> <p>Improper storage of equipment: Load line houses in and outside of the TNK BTRY containment. Rule 603 f CAD of 4-11-19. See attached photo's 23 and 27.</p> <p>Materials handling and spill prevention procedures and practices: Improper storage of oil containers outside of TNK BTRY containment. Rule 1102 CAD of 4-11-19. See attached photo's 23,27,31,34 and 36.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | silverr | 03/11/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401968864    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759746">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759746</a> |

|           |         |   |
|-----------|---------|---|
| 688401432 | loc pic | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759744">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4759744</a> |
|-----------|---------|---|

