

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 1. Overview of location taken at entrance facing northeast. Frack tanks stored with improper berm in northeast corner of location.



Photo 2. Overview of Grizzly wellheads. Stained soil and boards.

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 3. Stained soil and board.



Photo 4. Rathole open, stained soil, bucket full of oily fluid.

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 5. Bucket with oil fluid.



Photo 6. Stained soil, oily debris, cellar full of fluid.

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 7. Cellar full of fluid, oil on top, stained soil and oily debris.



Photo 8. Stained soil, oily debris.