

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2019

Submitted Date:

03/28/2019

Document Number:

685305785

FIELD INSPECTION FORM

Loc ID 320129 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 90615
Name of Operator: TUDEX PETROLEUM INC
Address: 2121 39TH AVE NE UNIT E
City: CALGARY State: AL Zip: T2E 6R7

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202757	WELL	PR	07/31/2008	OW	001-08162	CROFF 12-5	TA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Location			
Lease Road:			
Type	Access		
comment:	Access of maintained county road.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris that was stacked on concrete pumping unit base has been removed.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Chainlink fencing.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead		
Corrective Action:			Date:
Type: Other	#		
Comment:	Concrete pumping unit base.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:
Flaring:			
Type	<input style="width: 100%;" type="text"/>		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202757 Type: WELL API Number: 001-08162 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Wellhead location is part of Tudex Petroleum Inc. Equipment decommissioning, removal and salvage work.	stjohnw	03/27/2019
The remote well pumped to common production facility that is in the process of being closed.		
All the debris previously stacked on concrete pumping unit base has been removed.		
The concrete pumping unit base has been broken up and is ready for haul off and removal.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305792	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4776568