

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type		
	Comment:		
Corrective Action:		Date:	

Equipment:

	Type	#	Comment	Corrective Action	Date	corrective date
	Pump Jack	# 1				
			Comment:			
			Corrective Action:		Date:	
	Emission Control Device	# 0				
			Comment:			
			Corrective Action:		Date:	
	Horizontal Heated Separator	# 0				
			Comment:			
			Corrective Action:		Date:	
	Prime Mover	# 1				
			Comment: Electric motor			
			Corrective Action:		Date:	
	Gas Meter Run	# 0				
			Comment:			
			Corrective Action:		Date:	
	Ancillary equipment	# 1				
			Comment: Electric panel			
			Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240586 Type: WELL API Number: 123-08374 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection. At time of inspection there was open trench with exposed electric and gas lines.	silverr	03/28/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401738	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4776576