

Inspection Photos

Location Name: Staudinger 1-31H Location ID 424744

Inspection Date: 3/27/2019



Photo 1 – Location sign




Photo 2 – Leaking wellhead and impacted material/soil.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Staudinger 1-31H Location ID 424744

Inspection Date: 3/27/2019



Photo 3 – Northside damaged heater treater.



Photo 4 – Southside damaged treater and impacted material removed from within secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Staudinger 1-31H Location ID 424744

Inspection Date: 3/27/2019



Photo 5 – Inside secondary containment showing impacted material removed from containment area.



Photo 6 – South side of heater treater showing presumed area impacted by spill and damaged meter shed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Staudinger 1-31H Location ID 424744

Inspection Date: 3/27/2019



Photo 7 – Impacted material stockpiled on location.



Photo 8 – Piping for ECD warped by heat and coated in oil fro spill.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources