

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2019

Submitted Date:

03/28/2019

Document Number:

696100670

FIELD INSPECTION FORM

Loc ID 332990 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10311
 Name of Operator: SRC ENERGY INC
 Address: 1675 BROADWAY SUITE 2600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@srcenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286564	WELL	PR	12/11/2018	GW	123-24230	CHRISTIANSEN 35-15	SI

General Comment:

This is a WELL Inspection.
 Well is SI.
 Battery & ALL equipment is Shut-down.
 Centralized Battery serves 1 Location ID (332990).
 Centralized Battery formerly served 2 additional Location IDs (331048, 332906) (3-Wells: PA).
 Refer to FIR #696100343 and/or Location ID #332990 for Battery / Facility, Equipment info.

Follow-up to FIR #696100343 dated 03/01/2019.
 1 of 1 Corrective Actions has been addressed.
 1.) Unused Equipment at wellsite. Refer to Rule 603.f for guidance. (30 Days). See photo #1.
 Unused Equipment has been removed. See photo #2.

No Corrective Actions observed on this FIR.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Prior FIR: Unused Equipment at wellsite. Refer to Rule 603.f for guidance. (30 Days). See photo #1. This FIR: Unused Equipment has been removed. See photo #2.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:			Date:
Type:	#		
Comment:	Refer to FIR #696100343 and/or Location ID #332990 for additional Equipment info.		
Corrective Action:			Date:

Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.444437,-104.855314
Comment:	Centralized Battery serves 1 Location ID (332990). Centralized Battery formerly served 2 additional Location IDs (331048, 332906) (3- Wells: PA). Refer to FIR #696100343 and/or Location ID #332990 for Tanks & Berms info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 286564 Type: WELL API Number: 123-24230 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Observed production valves shut.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
There does NOT appear to be any produced H2O tanks / vaults at location.	evinsb	03/28/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100671	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4776656