

W-18-27
Api# 05-045-06542
Inspection # 689702935



W-18-27
Api# 05-045-06542
Inspection # 689702935



W-18-27
Api# 05-045-06542
Inspection # 689702935



Exposed 2" line along damaged road ditch.

W-18-27
Api# 05-045-06542
Inspection # 689702935



Fencing material off north east edge of location.

W-18-27
Api# 05-045-06542
Inspection # 689702935



Fencing material off north east edge of location.



Fencing material off north east edge of location.

W-18-27
Api# 05-045-06542
Inspection # 689702935



Rubber hose in the north west corner of location.

W-18-27
Api# 05-045-06542
Inspection # 689702935



Pieces of 2" pipe in reclaim area north of wells.

W-18-27
Api# 05-045-06542
Inspection # 689702935



Road ditch damaged by traffic.

W-18-27
Api# 05-045-06542
Inspection # 689702935



Road ditch damaged by traffic.