

## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



Location at the Entry



Location Sign

## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



Contents of containment open to wildlife.



Contents of containment open to wildlife.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



Erosion is evident along unsterilized slope at the east side of location .



BMP not maintained on NE edge of location.

## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



**BMP damaged and not maintained at the NW corner of location.**



**BMP damaged and not maintained at the NW corner of location.**



## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



Soil and Debris piled up on the west, North, and east side of location.



Soil and Debris piled up on the west, North, and east side of location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



Open trash containers on location.



Tracking onto CR 320 from location 334745. No tracking BMP in place.



## Inspection Photos

Location Name: [5-MILE RANCH #SG 523-26](#)

Location: 334745

FIR Doc # 692700010



Debris has been pushed over well head equipment



Staining around well head

