

Inspection Photos

API: 05-071-09062

Operator: ARP PRODUCTION COMPANY LLC

Inspection Date: 3/25/2019

Inspection Photos



Photo 1. Facing southwest along the access road. No BMP's are installed to prevent erosion along the side of the access road.

Inspection Photos



Photo 2. The cut slope is bare of vegetation and susceptible to erosion.

Inspection Photos



Photo 3. Water is leaking from the wellhead.