

# Inspection Photos

API: 05-071-06867

Operator: ARP PRODUCTION COMPANY LLC

Inspection Date: 3/25/2019

## Inspection Photos



**Photo 1.** Facing northwest at the location. Vegetation has not established.



## Inspection Photos



**Photo 2.** Facing east at the location. Vegetation is not established and there are signs of erosion.



## Inspection Photos



**Photo 3.** Facing towards the east side of the location. There is signs of sediment being deposited off location.



## Inspection Photos



**Photo 4.** Facing west at the north side of the location. There is signs of erosion in this area.



## Inspection Photos



**Photo 5.** Facing southeast at the location. Vegetation has not established in this area.