

Inspection Photos

API: 05-009-06627

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/27/2019

Inspection Photos



Photo 1. Facing north along the access road. Road continues past the location towards a stock tank. There is erosion along the road that need to be filled in and fixed.

Inspection Photos



Photo 2. Facing northwest toward the location. Vegetation has not established and there are undesirable weeds.

Inspection Photos



Photo 3. Facing west towards the location. There are bare areas with no vegetation establishment.

Inspection Photos



Photo 4. There are bare areas with no vegetation establishment.

Inspection Photos



Photo 5. There is a cattle guard that remains at the west side of the location.

Inspection Photos



Photo 6. Facing east at the location.

Inspection Photos



Photo 7. There is plastic pipe that remains at the center of the location.

Inspection Photos



Photo 8. Facing north toward the surrounding undisturbed pasture.