

Inspection Photos

API: 05-009-06629

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/27/2019

Inspection Photos



Photo 1. Facing north along the access road. Road continues past the location towards a stock tank. There is erosion along the road that need to be filled in and fixed.

Inspection Photos



Photo 2. Facing northeast toward the access road. This access road need to be reclaimed.

Inspection Photos



Photo 3. Facing northeast towards the location. There are bare areas with no vegetation establishment.

Inspection Photos



Photo 4. Facing southwest at the location.

Inspection Photos



Photo 5. Facing east at the undisturbed pasture.