

# Inspection Photos

API: 05-009-06637

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/27/2019

## Inspection Photos



**Photo 1.** Facing west at the beginning of the access road. Vegetation has not re-established in this area.

## Inspection Photos



**Photo 2.** Facing west along the access road. Vegetation has established along this portion of the road.

## Inspection Photos



**Photo 3.** There is a perimeter fence that remains in disrepair around the location.

## Inspection Photos



**Photo 4.** Facing southwest at the location.

## Inspection Photos



**Photo 5.** Facing west at the location.

## Inspection Photos



**Photo 6.** Facing southeast at the location.

## Inspection Photos



**Photo 7.** There is plastic pipe debris that remains at the center of the location.