

Inspection Photos

API: 05-009-06628

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/27/2019

Inspection Photos



Photo 1. Facing east toward the access road which has not been recontoured and reclaimed.

Inspection Photos



Photo 2. Facing east along the access road. Vegetation has not established along the road.

Inspection Photos



Photo 3. Facing north toward the northwest area of the location. Vegetation has not established in this area.

Inspection Photos



Photo 4. Facing east at the north side of the location. Vegetation has not established in this area.

Inspection Photos



Photo 5. Facing east at the north side of the location. Vegetation has not established in this area.

Inspection Photos



Photo 6. Facing northeast at the location. Vegetation has not established in this area.

Inspection Photos



Photo 7. Facing south at the location.

Inspection Photos



Photo 8. South side of the location facing northwest. Vegetation has not established in this area.

Inspection Photos



Photo 9. Facing east toward the surrounding undisturbed pasture.