

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2019

Submitted Date:

03/22/2019

Document Number:

675002064**FIELD INSPECTION FORM**Loc ID 414268 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------------------------------|
| Peicka, Conor | | conor.pesicka@state.co.us | All Inspections |
| Clark, Chris | | cogccnotifications@laramie-energy.com | All Inspections |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 414456 | WELL | PR | 12/09/2011 | GW | 045-18850 | KNOX 03-07C | PR |

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|---|------------------|
| Comment: | 911 / 1-800-891-6191 Nearest Access Not Posted | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: 04/22/2019 |

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| Type | # | corrective date |
|-----------------------------------|-----|-----------------|
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLS | STEEL AST | | , |

| | | | | | | | |
|--------------------|--|--|--|--|--|-------|--|
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Paint

| | | | | | | | |
|------------------|----------|--|--|--|--|--|--|
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |

Berms

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

| | | | | | | | |
|--------------------|---|--------------------------|-------------|---------|--------|-------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| AMINE | 1 | <50 BBLS | PLASTIC AST | | , | | |
| Comment: | | White chemical container | | | | | |
| Corrective Action: | | | | | | Date: | |

Paint

| | | | | | | | |
|------------------|----------|--|--|--|--|--|--|
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |

Berms

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Other | Adequate | Walls Sufficent | Base Sufficent | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

| | | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| CONDENSATE | 2 | 300 BBLS | STEEL AST | | , | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Paint

| | | | | | | | |
|------------------|----------|--|--|--|--|--|--|
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |

Berms

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| Inspected Facilities | | | | | | | | | |
|----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 414456 | Type: | WELL | API Number: | 045-18850 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Compaction | | | | |
| | | Gravel | | | | |
| Compaction | | | | | | |
| Berms | | | | | | |
| Gravel | | | | | | |

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| No Nearest Access posted | wentzeld | 03/22/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 401982812 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4771928 |
| 675002065 | Inspection 675002064 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4771921 |