

Inspection Photos

3/28/2019

Operator: VERDAD RESOURCES LLC # 10651

Location ID: 462872

Inspection Doc. Number: 682504684

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southwest corner of the location, facing east. Photo shows operator has installed a ditch/berm BMP along perimeter of the location. BMP does not appear to have been constructed in accordance with good engineering practices; BMPs have not been sufficiently compacted, remains unconsolidated materials and a potential source for sediment laden stormwater discharge.

Inspection Photos
Operator: VERDAD RESOURCES LLC # 10651
Location ID: 462872



Photo 2: Photo taken from the southwest corner of the location, facing north. See comments under photo 1.

Inspection Photos
Operator: VERDAD RESOURCES LLC # 10651
Location ID: 462872



Photo 3: Photo taken from the ditch/berm on the west end of the location, facing northeast. Photo shows operator has installed a ditch/berm BMP along perimeter of the location. BMP does not appear to have been constructed in accordance with good engineering practices; BMPs have not been sufficiently compacted, remains unconsolidated materials and a potential source for sediment laden stormwater discharge.



Photo 4: Photo taken from the northwest corner of the location, facing east. Photo shows ditch/berm along perimeter of location. Photo also shows berm along perimeter of the pad.



Photo 5: Photo taken from the ditch/berm on the east end of the location. Photo shows operator has installed a ditch/berm BMP along perimeter of the location. BMP does not appear to have been constructed in accordance with good engineering practices; BMPs have not been sufficiently compacted, remains unconsolidated materials and a potential source for sediment laden stormwater discharge.



Photo 6: Photo taken from the northeast corner of the location, facing south. See comments under photo 5

Inspection Photos
Operator: VERDAD RESOURCES LLC # 10651
Location ID: 462872



Photo 7: Photo taken from the south end of the location, facing east. See comments under photo 5.



Photo 8: Photo shows culvert installed and access road.