

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2019

Submitted Date:

03/29/2019

Document Number:

688000299**FIELD INSPECTION FORM**
 Loc ID 317231 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 53790Name of Operator: MARKUS PRODUCTION, INCAddress: 39 FAIRWAY LANECity: LITTLETON State: CO Zip: 80123**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Mark	(720) 350-8858	mark@markusproduction.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107649	PIT	AC			-	JOLLY 41X-6	EI
119049	PIT	AC			-	CHARLES JOLLY 41X-6	EI

**General Comment:**

Well reported PA 12/16/2014 final reclamation should have been completed by 12/16/2015. Form 27 for pit closures required.

Inspected Facilities								
Facility ID:	107649	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	119049	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 107649      Lat: 39.827663      Long: -103.577262

Reference Point:       Other:       Length:       Width:

**Lining:**Liner Type: Liner Condition: Comment: Pit remains open, no Form 27 has been recieved by COGCC for proper closure.Corrective Action: Immediately submit a Form 27 describing the closure plan for this pit.Date: 12/16/2015**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: 

Type: Produced Water      Lined: NO      Pit ID: 119049      Lat: 39.827990      Long: -103.577517

Reference Point:       Other:       Length:       Width:

**Lining:**Liner Type: Liner Condition: Comment: Pit remains open, no Form 27 has been recieved by COGCC for proper closure.Corrective Action: Immediately submit a Form 27 describing the closure plan for this pit.Date: 12/16/2015**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Inspector Name: YOUNG, ROB

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		
Corrective Action		
		Date:

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000300	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778325">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778325</a>