

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2019

Submitted Date:

03/29/2019

Document Number:

681701196

**FIELD INSPECTION FORM**

Loc ID 451421 Inspector Name: Arauza, Steven On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	
Wentzel, Dougo		dougo.wentzel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Bankert, Wayne		wbankert@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453889	SPILL OR RELEASE	AC	03/02/2018		-	Bruton 30-03	EI

**General Comment:**

COGCC Environmental Inspection of tank battery, conducted in response to verbal notification from the operator of a potential release inside of tank battery containment.

Tank battery consists of four (4) 400 bbl steel ASTs labeled to contain condensate/produced water, which are located inside of lined metal containment berm. On date of inspection, tank battery berm contained approximately 6-9 inches of fluids (water with hydrocarbon sheen and odor). See photos. No visible tears or holes were observed in visible portion of tank battery liner during inspection. No active source of the fluids observed inside of containment was determined by inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: Yes \_\_\_\_\_

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

**Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 453889 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: \_\_\_\_\_

Comment: Presence of fluid inside of tank battery containment likely explained by accumulation of snowmelt. Fluids constitute oily waste, due to presence of hydrocarbon odor and sheen. See photos.

Corrective Action: Remove and properly dispose of oily waste, per Rule 907.e. Submit information regarding final disposition of fluids to the COGCC via a Field Inspection Report Response form. If fluids are determined to be the result of a spill or release from the production facility, submit an eForm 19 Spill Report per Rule 906.b.

Date: 04/12/2019

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Spill ID #453889 remains active for the subject facility. Supplemental eForm 19 received 2/21/2018 (doc #401549719) includes the following COGCC comment: "Benzene concentration is above Table 910-1 on sample 30-03-SS1 (0.29 mg/kg). The request for closure box was unchecked. Another round of samples is required to confirm compliance with Table 910-1. 3 samples, including one at the center of the spilled area is suggested." Remediation Project #11230 was approved to address impacts. Operator has not provided any project updates after Initial F27 (doc #401606653) was approved on 4/17/2018.

Corrective Action: Submit an update for Spill #453889 via an eForm 19 Supplemental Report. Operator may include a closure request indicating that work was proceeding under approved Remediation Project #11230. Submit an eForm 27 Supplemental Report to provide a project status update and additional documentation for Remediation Project #11230.

Date: 04/29/2019

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701199	20190327 Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778501</a>