

Inspection Photos

API: 05-009-06014

Operator: JONES ENERGY LTD

Inspection Date: 3/27/2019

Inspection Photos



Photo 1. Facing southwest at the beginning of the access road. There are undesirable weeds along the road and desirable vegetation has not established.

Inspection Photos



Photo 2. Facing southwest at the beginning of the access road. There are undesirable weeds along the road and desirable vegetation has not established.

Inspection Photos



Photo 3. The location is mostly bare of vegetation. It does not appear that any effort has been made at reclamation.

Inspection Photos



Photo 4. Facing northeast at the location. The location is mostly bare of vegetation. It does not appear that any effort has been made at reclamation.

Inspection Photos



Photo 7. Facing east at the surrounding CRP pasture.