

Maralex Resources Inc.

Api # 05-077-089853

Inspection # 675002099



Photo of location

Maralex Resources Inc.

Api # 05-077-089853

Inspection # 675002099



No Wellhead sign debris around pump jack



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.

Api # 05-077-089853

Inspection # 675002099



Photo of Tank Battery. Berm has debris around it and fluid in containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.
Api # 05-077-089853
Inspection # 675002099



Debris around tank and containment



Debris and trash on location

Maralex Resources Inc.
Api # 05-077-089853
Inspection # 675002099



Sediment running on and off location



Sediment running off location

Maralex Resources Inc.
Api # 05-077-089853
Inspection # 675002099



Erosion on location



Erosion from location moving sediment off location

Maralex Resources Inc.
Api # 05-077-089853
Inspection # 675002099



Erosion leaving location from BMP not being maintained



Erosion leaving location

Maralex Resources Inc.
Api # 05-077-089853
Inspection # 675002099



Erosion from location going down access road



Erosion from upper location coming down access road and running onto location

Maralex Resources Inc.
Api # 05-077-089853
Inspection # 675002099



Erosion from location going down the access road



Erosion leaving location on entrance side of location