

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/29/2019

Submitted Date:

03/29/2019

Document Number:

675002096

FIELD INSPECTION FORM
 Loc ID 312609 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222011	WELL	SI	05/01/2012	GW	077-08613	SOUTH SHALE RIDGE 7-24	SI

General Comment:

This is a follow up inspection from Doc#689401339 dated 6/7/18 and 675001726 dated 1/9/19 . Required Corrective Action (s) items noted in previous inspections have been satisfied.
This well is not part of Order 1V-609.

01/14/2019- Edited to remove CA date under tank entry. - Conor Pesicka

Location			
Lease Road:			
Type	Access		
comment:	Access road to location has multiple areas of erosion across roadway and sediment migration down gradient of road surface. This location is a federal surface hence the inspection is being forwarded to a BLM representative so they may respond to the operator on what actions should be implemented. The road does not meet the COGCC stormwater rules for erosion and sediment migration. See attached photos.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	08/07/2018
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No Wellhead sign		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	02/11/2019
Type	TANK LABELS/PLACARDS		
Comment:	tank labels missing information and has inaccurate information		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	03/11/2019
Emergency Contact Number:			
Comment:	970-858-8550 911 and Nearest Access NOT Posted		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/29/2019
Good Housekeeping:			
Type	OTHER		
Comment:	See storm water		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:			

Corrective Action:					Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	300 BBLs	Open Top		,	
Comment:		See tanks labels under signs/markers on prior inspections				
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate		
Comment:		Dirt berm or containment, full of fluid				
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 04/29/2019	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	222011	Type:	WELL	API Number:	077-08613	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Shut in, Well last produced April 2010. MIT on 2/19/2015 Doc#400797603.</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion not being controlled on the location at this time.
BMP's not in place or maintained.
Sediment running onto and off location causing erosion

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 04/29/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675002100	Inspection 675002096 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778912