

**Inspection Photos**  
**Location Name: VPR C 120**  
**API #: 05-071-07792**  
**Insp. Doc. # 695100385**



**PHOTO 1: LOCATION/ WELLHEAD**



**PHOTO 2: LOCATION SIGN/ METER RUN**



**Inspection Photos**  
**Location Name: VPR C 120**  
**API #: 05-071-07792**  
**Insp. Doc. # 695100385**



**PHOTO 3: WELLHEAD IS SOAKED WITH AN OILY SUBSTANCE THAT IS IMPACTING A 5' BY 4' RADIUS AROUND WELLHEAD**



**PHOTO 4: IMPACTED SOIL APP. 4' BY 3' TO THE NORTH OF WELLHEAD**



**Inspection Photos**  
**Location Name: VPR C 120**  
**API #: 05-071-07792**  
**Insp. Doc. # 695100385**



**PHOTO 4: SPOT OF IMPACTED SOIL AWAY FROM WELLHEAD  
TO THE EAST APP. 25'.**

