

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2019

Submitted Date:

04/01/2019

Document Number:

690003193

FIELD INSPECTION FORM

Loc ID 330949 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256762	WELL	SI	12/01/2018	GW	123-19922	HSR-WAGNER 1-25AX	SI
436593	WELL	PR	06/18/2014	SI	123-39189	BAREFOOT 30C-25HZ	PR
436596	WELL	PR	02/02/2015	OW	123-39191	BAREFOOT 31C-25HZ	PR
436704	WELL	PR	02/03/2015	OW	123-39231	BAREFOOT 30N-25HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No
 Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 2		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: Battery location number: 436706						Date:		
Corrective Action:						Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS			
METHANOL	1	OTHER	STEEL AST		40.202970,-104.943570			
Comment:						Date:		
Corrective Action:						Date:		
Paint								
Condition								
Other (Content)								
Other (Capacity)	350 Gal							
Other (Type)								
Berms								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate				
Comment:						Date:		
Corrective Action:						Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS			
OTHER	1	OTHER	STEEL AST		,			
Comment: Corrosion inhibitor						Date:		
Corrective Action:						Date:		
Paint								
Condition								
Other (Content)								
Other (Capacity)								
Other (Type)								
Berms								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Comment: same as methanol tank.						Date:		
Corrective Action:						Date:		
Venting:								
Yes/No	NO							
Comment:						Date:		
Corrective Action:						Date:		
Flaring:								
Type								
Comment:						Date:		
Corrective Action:						Date:		

Inspected Facilities

Facility ID: 256762 Type: WELL API Number: 123-19922 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: 401636069 06 (N) -00

Corrective Action: _____ Date: _____

Facility ID: 436593 Type: WELL API Number: 123-39189 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 436596 Type: WELL API Number: 123-39191 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 436704 Type: WELL API Number: 123-39231 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Monday, April 1, 2019 at 10:08, I, Craig Carlile conducted an on-site inspection at: 330949, BAREFOOT 30C-25HZ</p> <p>Operated by: Anadarco While there I observed: Three producing wells and one shut in awaiting plugging. Possible compliance issues observed: No: ? Routine Inspection. This is a summary of the inspection report.</p>	carlilec	04/01/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003194	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780350