

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401939702
Date Received:
02/14/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Kevin Kane	303-893-2503	kkane@bayswater.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 696100072
Inspection Date: 02/06/2019 FIR Submit Date: 02/06/2019 FIR Status:

Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC Company Number: 10261
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 306743

Location Name: HESTER-67N66W Number: 31SWNW County:
Qtrqr: SWN Sec: 31 Twp: 7N Range: 66W Meridian: 6
W
Latitude: 40.532560 Longitude: -104.829420

FACILITY - API Number: 05-123- -00 Facility ID: 306743

Facility Name: HESTER-67N66W Number: 31SWNW
Qtrqr: SWN Sec: 31 Twp: 7N Range: 66W Meridian: 6
W
Latitude: 40.532560 Longitude: -104.829420

CORRECTIVE ACTIONS:

1 CA# 122377

Corrective Action: Cutoff & permanently cap casing and/or install a temporary casing safety cap. Comply with Rule 605.c. Date:

Response: CA COMPLETED Date of Completion: 02/14/2019

Operator Comment: Corrective action completed per Operator comments included on comment tab

COGCC Decision: Approved

COGCC Representative: Follow-up FIR #696100402 dated 03/07/2019 confirms Casing has been cut & capped below ground surface, addressing the Corrective Action.

OPERATOR COMMENT AND SUBMITTAL

Comment: The Hester 31-23 downholle plugging was completed per approved Form 6 intent, document 401836058 on 12/18 2018. The rig moved on 12/19/2018 leaving the 8 5/8' wellhead with cement at surface. Cattle fencing was installed to protect the wellhead. On 2/14/2019 the 8 5/8" wellhead was cut off and capped at a depth of 8 feet below surface. Solid cement was encountered at 5 feet below surface. The area surrounding the capped wellhead is currently dug out and waiting on soil samples to be analyzed. The disturbed wellhead area will be enclosed with temporary orange construction fencing until the excavation is backfilled.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Kane

Signed: _____

Title: Operations Manager

Date: 2/14/2019 10:49:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401939702	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files