

Inspection Photos

Location: Vaneta 1-32D

Inspection Date: 3/11/19

Photos taken by Kris Neidel



Photo 1- Vaneta injection well, 057-06467 load area. Note truck present, it was actively unloading. Tanks have oil staining where they have overflowed. Staff was present to inspect the area of spill number 463151. The area of impact appears to be the area where the frac tanks were set



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location: Vaneta 1-32D
Inspection Date: 3/11/19
Photos taken by Kris Neidel



Photo 2- Vaneta injection well, 057-06467 load area. Note truck present, it was actively unloading. Tanks have oil staining where they have overflowed. Staff was present to inspect the area of spill number 463151. The area of impact appears to be the area where the frac tanks were set