

Inspection Photos  
Location: Vaneta 1-32D, DAF  
Inspection Date: 3/11/19  
Photos taken by Kris Neidel



**Photo 1-The building contains the DAF unit. The tanks on the left of photo contain fluid that has been brought to location by truck, prior to treatment. Note the building built around the secondary containment.**

