

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2019

Submitted Date:

04/02/2019

Document Number:

694500078

FIELD INSPECTION FORMLoc ID 324752 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|--|---------|
| Fischer, Alex | | alex.fischer@state.co.us | |
| Waldron, Emily | | emily.waldron@state.co.us | |
| James, general | | sandridgeenvironmental@sandridgeenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|-------------------------------------|--------|-------------|------------|---------|-------------------|-------------|
| 463141 | CENTRALIZED EP WASTE MGMT FAC | XX | 03/11/2019 | | - | VANETA DAF 67N90W | EI |

General Comment:

On 3/11/2019 COGCC Environmental staff inspected DAF pilot project. The pilot project details can be found in document number 401590362. Sandridge Staff accompanied COGCC staff, Kris Neidel on a tour of the facility. The DAF was operating at the time of inspection. The building seen in attached photo is built around liner/steel secondary containment typical of other Sandridge tank batteries and triplex pumps. The following is inside the DAF building: gravel floor, a work space for an attendant who is monitoring the efficiency of the DAF unit, field test kits and supplies, a work space for the attendant, tank for effluent, storage of consumables, etc. The process operates at near atmospheric pressure. The operator should ensure that the building is properly placarded per COGCC 210.d. The operator should ensure that COGCC Fire Prevention Rules, 606A are being followed. Prior to the submittal of this inspection, COGCC staff has discussed placarding rules with Sandridge staff.

Inspected FacilitiesFacility ID: 463141 Type: CENTRALIZE API Number: - Status: XX Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694500079 | photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780921 |