

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | Pipe | | |
| Corrective Action: | | | Date: |

Equipment:

| | | | |
|--------------------|-----|--|-----------------|
| | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | |
| Comment: | Battery nearest well is API 05-123-17410 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | | |
|------------------|--|--|--|
| Condition | | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 249607 Type: WELL API Number: 123-17410 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in at flow line connection to flow line.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>On Tuesday, April 2, 2019 at 09:42, I, Craig Carlile conducted an on-site inspection at: 329477, MAYER-63N67W 22SWSW Operated by: Anadarco While there I observed: Well(s) Shut In Possible compliance issues observed: No: ? Routine Inspection. This is a summary of the inspection report.</p> | carlilec | 04/02/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 690003216 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781706 |