

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2019

Submitted Date:

04/02/2019

Document Number:

690003233

FIELD INSPECTION FORM

Loc ID 319447 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243497	WELL	PR	10/01/2017	GW	123-11289	UPRR 42 PAN AM UNIT X TRUE 1	PR
417291	WELL	PR	10/01/2017	OW	123-31631	OLIN FEDERAL 21-31	PR
417298	WELL	PR	10/01/2017	OW	123-31633	OLIN FEDERAL 25-31	PR
417304	WELL	PR	10/01/2017	OW	123-31636	OLIN 30-31	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity) 210 Bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shared with crude oil tanks.	Date:	
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		40.184520,-104.824850

Comment:		Date:	
Corrective Action:		Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:		Date:	
Corrective Action:		Date:	

Venting:

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	Date:	
Comment:		Date:	
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>243497</u>	Type:	<u>WELL</u>	API Number:	<u>123-11289</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>417291</u>	Type:	<u>WELL</u>	API Number:	<u>123-31631</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>417298</u>	Type:	<u>WELL</u>	API Number:	<u>123-31633</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>417304</u>	Type:	<u>WELL</u>	API Number:	<u>123-31636</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On Tuesday, April 2, 2019 at 12:37, I, Craig Carlile conducted an on-site inspection at: 319447 OLIN, 30-31 Operated by: Anadarco While there I observed: Well(s) Producing, production equipment and battery Possible compliance issues observed: No: ? Routine Inspection. This is a summary of the inspection report.</p>	carlilec	04/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003234	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781715