

Caerus Piceance LLC .
Api # 05-045-14157
Inspection # 675002104



Photo of location

Caerus Piceance LLC .
Api # 05-045-14157
Inspection # 675002104



Wellhead signs heavy rutting, loss of compaction

**Caerus Piceance LLC .
Api # 05-045-14157
Inspection # 675002104**



Photo of Tank Battery.

**Caerus Piceance LLC .
Api # 05-045-14157
Inspection # 675002104**



Stained gravel inside containment



Oily substance staining outside of tank

Caerus Piceance LLC .
Api # 05-045-14157
Inspection # 675002104



Heavy erosion on sw corner of location



Sediment running off west side of location outside of ditch

Caerus Piceance LLC .
Api # 05-045-14157
Inspection # 675002104



Sediment moving off South side of location