

Caerus Piceance LLC .
Api # 05-045-09548
Inspection # 675002106



Photo of location at entrance

Caerus Piceance LLC .
Api # 05-045-09548
Inspection # 675002106



Wellhead signs heavy rutting, loss of compaction

Caerus Piceance LLC .
Api # 05-045-09548
Inspection # 675002106



Photo of Tank Battery.



Caerus Piceance LLC .
Api # 05-045-09548
Inspection # 675002106



Erosion on SW side of tank battery



Erosion is evident along unsterilized slope at the north side of location .