

Caerus Piceance LLC .
Api # 05-045-10411
Inspection # 675002112



Photo of location at entry

Caerus Piceance LLC .
Api # 05-045-10411
Inspection # 675002112



Wellhead signs

Caerus Piceance LLC .
Api # 05-045-10411
Inspection # 675002112



Photo of Tank Battery.

Caerus Piceance LLC .
Api # 05-045-10411
Inspection # 675002112



Waddles on south side of location



Erosion is evident along unsterilized slope on the east side of location .