

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2019

Submitted Date:

04/01/2019

Document Number:

675002104

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
334355 _____ Wentzel, Dougo _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
, Caerus		COGCC.inspections@caerus oilandgas.com	All inspection
Peicka, Conor		conor.pesicka@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290608	WELL	PR	05/08/2008	GW	045-14159	G. JONES 35-44B	PR
290609	WELL	PR	08/01/2018	GW	045-14158	G. JONES 35-44A	PR
290610	WELL	PR	01/29/2013	GW	045-14157	G. JONES 35-34A	PR
290671	WELL	PR	05/16/2008	GW	045-14169	HELEY 35-44C	PR
290672	WELL	PR	01/07/2011	GW	045-14168	HELEY 35-34D	PR
290673	WELL	PR	04/25/2008	GW	045-14167	HELEY 35-34C	PR
290674	WELL	PR	05/12/2008	GW	045-14166	HELEY 35-44D	PR
291294	WELL	PR	01/29/2013	GW	045-14324	G. JONES 35-34B	PR

General Comment:

[Routine FIU General Field Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	866-580- 9382 /911		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Observed stained gravel inside containment and oily substance on outside of tank		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS 48-hrs To perform cleanup. 5 days to contact Area EPS		Date: 04/07/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		

Comment:		
Corrective Action:		Date:

Equipment:		corrective date
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 8	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 8	
Comment:		
Corrective Action:		Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
AMINE	1	<50 BBLs	PLASTIC AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	See housekeeping			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290608	Type:	WELL	API Number:	045-14159	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	290609	Type:	WELL	API Number:	045-14158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	290610	Type:	WELL	API Number:	045-14157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	290671	Type:	WELL	API Number:	045-14169	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	290672	Type:	WELL	API Number:	045-14168	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	290673	Type:	WELL	API Number:	045-14167	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	290674	Type:	WELL	API Number:	045-14166	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	291294	Type:	WELL	API Number:	045-14324	Status:	PR	Insp. Status:	PR

Producing Well

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Drains						
		Compaction				
Berms						
Compaction						
		Gravel				

Comment: Stormwater erosion not being controlled on the location at this time. On the SW side of location, sediment is able to move off locations due to ditch full of sediment and stormwater not being completely directed into present ditch or trap. Also on SW corner of location, ditch runs into a catch basin that needs repaired or maintenance. BMP's not in place or need maintained.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 05/02/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675002115	Inspection 675002104 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781935