

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2019

Submitted Date:

04/02/2019

Document Number:

696100698

FIELD INSPECTION FORM

Loc ID 332774 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 17 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspections@srcenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292226	WELL	PR	01/15/2015	GW	123-26267	SCHANK J 35-1	PR
293137	WELL	PR	07/01/2017	GW	123-26483	SCHANK J 36-31	PR
294029	WELL	PR	07/01/2017	GW	123-26672	SCHANK J 35-27	PR
447045	TANK BATTERY	AC	07/29/2016		-	SCHANK J-65N66W 35NENE	AC

General Comment:

This is a WELL & BATTERY inspection.
3-wells: PR
Follow-up to FIR #696100041 dated 01/31/2019.
1 of 1 Corrective Actions have been addressed.
1.) No Emergency number posted at wellsites.
Emergency number NOW posted at wellsites. See photos #1-6.

No Corrective Actions observed on this FIR.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	From prior FIR: No emergency contact number shown at 3 wellsites. 1.) Schank J 35-1 2.) Schank J 35-27 3.) Schank J 36-31 This FIR: Emergency contact number NOW posted at 3 wellsites.		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	3 - wellsites: Chain link.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Chain link.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Chain link. Surrounded by earth berms.		
Corrective Action:			Date:
Type	TANK BATTERY		

Comment: Chain link.			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	3 - wellsites: Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	ECD scrubbers.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	ECD #1: controls crude oil tank VOCs. ECD #2: controls separator VOCs. Pilots: ON		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	48 Bbls.				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ crude oil tanks & 60 Bbls. produced H2O vault.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	CONCRETE SUMP/VAULT		
Comment:					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)	60 Bbls.				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ crude oil tanks & 48 Bbls. produced H2O vault.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.360845,-104.736056
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ produced H2O vaults.				
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID:	<u>292226</u>	Type:	<u>WELL</u>	API Number: <u>123-26267</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>PR.</u>			
Corrective Action:		Date:		
Facility ID:	<u>293137</u>	Type:	<u>WELL</u>	API Number: <u>123-26483</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>PR.</u>			
Corrective Action:		Date:		
Facility ID:	<u>294029</u>	Type:	<u>WELL</u>	API Number: <u>123-26672</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>PR.</u>			
Corrective Action:		Date:		
Facility ID:	<u>447045</u>	Type:	<u>TANK</u>	API Number: <u>-</u> Status: <u>AC</u> Insp. Status: <u>AC</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100699	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781941