



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Ancillary equipment

# 1

corrective date

Comment: [TELEMETRY EQUIPMENT](#)

Corrective Action:

Date:

Type: Other

# 1

Comment: [BREADENHEAD IS PLUMBED TO SURFACE](#)

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Electrical transformers, breaker panel and meter.](#)

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 258176 Type: WELL API Number: 071-07085 Status: PR Insp. Status: PR

**Producing Well**

Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100420	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782241">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782241</a>