



**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |       |            |
|--------------------|--|-------|------------|
| Comment:           | Emergency contact number is damaged. See attached photo. | Date: | 04/30/2019 |
| Corrective Action: | Install sign to comply with Rule 210.b.                  |       |            |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Panel    |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 1 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 248166 Type: WELL API Number: 123-15964 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: OFF Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401987314    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775511">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775511</a> |
| 674301815    | Photo                | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775503">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775503</a> |