

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: 6' Chain link fence with Barb wire on top.

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Prime Mover # 1

Comment: Electric motor

Corrective Action:

Date: _____

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: _____

Type: Other #

Comment: Electrical boxes.

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 240933 Type: WELL API Number: 123-08721 Status: PR Insp. Status: PR

Producing Well

Comment: Well appears to be leaking at stuffing box.

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/11/2018

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday March 27, 2019 at approximately 0830 I, Inspector Justin Medina, conducted an on-site inspection at 1 UPRR 42 PAN AM AE, at 123-08721 in Weld County Colorado.</p> <p>While there, I observed Producing well During this inspection the following possible compliance issues were observed: What appears to be leaking stuffing box on well. See picture 1 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. See inspection Document # 691400996. Same issue with Corrective action date of 10-11-18</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection</p>	medinaj	03/27/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401987150	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775343
685100724	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4775336